

#### NTSB National Transportation Safety Board


Office of Aviation Safety

# Fatigue Cracks and Ineffective Repairs

Matthew R. Fox, Ph.D., Materials Laboratory

Brian K. Murphy, Structures Group Chairman


## Wing Structure











### Repair Doublers














# Fracture Sequence



### Fracture Sequence



### Fracture Sequence





NTSB